


# 720 Series

## ENCLOSED WIRING



## WARNING

It is good practice to separate the High Current, High Voltage AC power inputs from the High Current, High Voltage motor phase outputs. Also, keep the High Current, High Voltage connections separated from the Low Voltage motor sensor signals and sensor power supply lines to reduce crosstalk and possible noise/interference issues. The Enclosed models have 3 endplate conduit holes for this purpose.